



Alan C. Lloyd, Ph.D.  
Secretary for  
Environmental  
Protection

# California Regional Water Quality Control Board

## Central Valley Region

Robert Schneider, Chair



Arnold  
Schwarzenegger  
Governor

### Sacramento Main Office

11020 Sun Center Drive #200, Rancho Cordova, California 95670-6114  
Phone (916) 464-3291 • FAX (916) 464-4645  
<http://www.waterboards.ca.gov/centralvalley>

**APPROVED**

author \_\_\_\_\_

senior JR \_\_\_\_\_

12 July 2005

CERTIFIED MAIL #  
7003 0500 0004 7907 8921

CERTIFIED MAIL #  
7003 0500 0004 7907 8938

Steven P. Case  
McGrath North Mullin & Kratz, PC LLO  
Suite 3700 First National Tower  
1601 Dodge Street  
Omaha, Nebraska 68102

Con Agra Foods, Inc  
Box 2000  
One ConAgra Drive  
Omaha, Nebraska 68102



CERTIFIED MAIL #  
7003 0500 0004 7907 8945

Monfort, Inc.  
John N. Simons  
1170 Promontory Circle  
Greely, Colorado 80634

### ***TENTATIVE CLEANUP AND ABATEMENT ORDER, DIXON BUSINESS PARK, DIXON, SOLANO COUNTY, CALIFORNIA***

This letter serves to acknowledge receipt of your April 28, 2005 letter and attached exhibits and constitutes the Regional Board's response to comments raised therein. These comments were also prepared with the input of the Regional Board's legal counsel on this matter, Mr. David Coupe. Also, enclosed is the *Tentative Cleanup and Abatement (Order), Dixon Business Park, Dixon, Solano County*. Staff of the Central Valley Regional Water Quality Control Board (Regional Board) request that parties named in the Order review it and submit comments by **12 August 2005** in order that consideration maybe given prior to the Regional Board Meeting. Regional Board staff anticipate that a hearing for this Order will be conducted during the September 15 and 16, 2005 Board Meeting.

#### **1. PRIOR INVESTIGATIONS AND WORK**

##### **Page 2 and Page 3 (Paragraph 13):**

You make the following statements that "ConAgra and Monfort, with agency approval have remediated the site" (page 2) and "Following the remediation Monfort, ConAgra and McLaughlin were all advised by California regulatory agencies, that no further monitoring or work would be required" page 3; see also Composite Exhibit 3).